# TMUSB Device Driver (for Windows 10 or later OS)

| | |
|---|---|
| Code | Ver.8.00e |
| Uploaded date | 2026/3/17 |
| File size | 1,574KB |
| Explanation | This download page is for TMUSB Device Driver Ver.8.00e that can be installed on Windows 10 or later.<br>TMUSB Device Driver Ver.7.10c can be installed on OS earlier than Windows 10.<br><br>This is a USB device driver for EPSON TM/EU/BA Series.<br>This module is a revision program for the USB communications department of OPOS, OPOS.NET, APD, JavaPOS, TM-J9000/J9100 Driver, TM-S1000 Driver and some utilities.<br>The TMUSB Device Driver is installed automatically when installing the Advanced Printer Driver.<br><br>**[Changes from Ver.8.10d to Ver.8.00e]**<br>New support OS]<br>Windows 11 ARM64<br>Windows server 2025<br><br>**[Support OS]**<br>Windows 11<br>Windows 10 (32/64 bit)<br>Windows Server 2025 (64 bit)<br>Windows Server 2022 (64 bit)<br>Windows Server 2019 (64 bit)<br>Windows Server 2016 (64 bit)<br><br>**[Note]**<br>You can check the version of TMUSB Device Driver installed in PC by one of the following methods.<br>> Able to check from device manager of PC if PC is connecting to the printer.<br>> Able to check from the property of the below file in PC.<br>C:¥Windows¥System32¥drivers¥TMUSBXP.sys or TMUSB64.sys<br>When some problems occur under the USB environment with the TM-S1000 Driver, TM-J9000/J9100 Printer Driver For Bank, OPOS ADK, Advanced Printer Driver, JavaPOS ADK, OPOS.NET ADK the problem of the USB environment can be cleared by using this program.<br>Please do not install TMUSB device driver in the environment that uses TMCOMUSB serial emulation driver. Please reinstall TMCOMUSB serial emulation driver if you install TMUSB device driver |

| | |
|---|---|
| Code | Ver.8.00e |
| Date de téléchargement | 2026/3/17 |
| Taille du fichier | 1,574KB |
| Explication | Cette page de téléchargement concerne le pilote de périphérique TMUSB version 8.00e, compatible avec Windows 10 et versions ultérieures.<br>Le pilote de périphérique TMUSB version 7.10c est compatible avec les systèmes d'exploitation antérieurs à Windows 10.<br>Il s'agit d'un pilote USB pour les imprimantes EPSON des séries TM/EU/BA.<br>Ce module est un programme de mise à jour pour la partie communication USB des systèmes OPOS, OPOS.NET, APD, JavaPOS, ainsi que pour les pilotes TM-J9000/J9100 et TM-S1000 et certains utilitaires.<br>Le pilote de périphérique TMUSB est installé automatiquement lors de l'installation du pilote d'imprimante avancé. |

**[Modifications apportées entre la version 8.10d et la version 8.00e]**
[Nouveau système d'exploitation pris en charge]
Windows 11 ARM64
Windows server 2025

**[Systèmes d'exploitation pris en charge]**
Windows 11
Windows 10 (32/64 bit)
Windows Server 2025 (64 bit)
Windows Server 2022 (64 bit)
Windows Server 2019 (64 bit)
Windows Server 2016 (64 bit)

**[Note]**
Vous pouvez vérifier la version du pilote de périphérique TMUSB installée sur votre PC par l'une des méthodes suivantes :
> Vérifiez dans le Gestionnaire de périphériques si votre PC est connecté à l'imprimante.
> Consultez les propriétés du fichier suivant sur votre PC :
C:¥Windows¥System32¥drivers¥TMUSBXP.sys ou TMUSB64.sys
En cas de problèmes de connexion USB avec les pilotes TM-S1000, TM-J9000/J9100 (pour les banques), OPOS ADK, Advanced Printer Driver, JavaPOS ADK et OPOS.NET ADK, ce programme permet de résoudre ces problèmes.
N'installez pas le pilote de périphérique TMUSB dans un environnement utilisant le pilote d'émulation série TMCOMUSB.
Réinstallez le pilote d'émulation série TMCOMUSB si vous installez le pilote de périphérique TMUSB.